

R

YESHIVA UNIVERSITY

Annual Fire Safety Report

October 1, 2023

Israel Henry Beren Campus

Murray Hill section of Manhattan

(Including The Benjamin Residence Hall of Cardozo School of Law)

FIRE SAFETY REPORTING AND ISCLOSURE POLICY

Introduction

As required by the Higher Education Opportunity Act ("HEOA"), Yeshiva University (the "University" or "YU") has established the following reporting and disclosure procedures with respect to fire safety in oncampus student housing for the Beren Campu(sconsisting of several buildings in the Murray Hill section of Manhattan) The reporting and disclosure requirements described below apply only to fires that occur in the University's Beren on-campus student housing that owned or controlled

າ	Λ	ว	1
Ζ	υ	Ζ	

Name of Residence	Fires and Cause	Injuries	Deaths	Value of Damages
BROOKDALE HALL	0	0	0	0
SCHOTTENSTEIN HALL	0	0	0	0
151 EAST 36TH STREET	0	0	0	0
150 EAST 35TH STREET	0	0	0	0
THE BENJAMIN – 148 LEXINGTON	0	0	0	0

Fires

Apartment Housing (AH)

Address of Residence

Relevant Fire Safety Definitions

For the purposes of the reporting and disclosure describedherein, the University defines the relevant terms as follows.

- "Fire": Any instance of open flame or othe burning in a place not intended to contain the burning or in an uncontrolled manner.
- "Cause of Fire": The factor σ factors that give rise to a fire,including intentional action, unintentional, mechanical failure, or an act of nature.
- "Fire- related inju ry": Any instance in which a person is injured as a restuble fire.
 These included injuries sustained from natural or accidental ca 0 Tw 12.5d [(r a)-Tj -0 (s)T)

At times, the University also houses studentism the following apartment buildings (AH):

• 251 Lexington Avenue, Man hatt an (Apartment Housing – AH)

This dwelling consists of multiple apartmentunits used, in part, for student housing for the Beren Campus. This building is managed by a thirdparty management company which also leases apartments to other private terrats. The management company is responsible for providing Fire Safety Plan and Evacuation procedures to residents and ensuring that the building adheres to all New York City Building Department and Fire Department regulations. Hallways in the building have sprinklers, and each apartment has battery operated smoke/carbon monoxide detectors.

• 30 Park Avenue, Manhattan (Apartment Housing - AH)

This dwelling is owned and managed by a third partyand consists of multiple apartment units,

Portable Electrical Appliances, Smoking, and Open Flames in a Housing Facility

Rules- In general, residents are expected to maintain adequate standads of cleanliness to avoid fire hazards and must not obstruct sidewalks, entrances, passages, fire escapes, elevators, lobbies stairways, corridors, or halls with personal property. The following items are prohibited in the residence hals and will be confiscated:

- Flammable decorations
- Natural or artificial trees
- Electric heaters, air conditioners, hot plate burners, toastersoaster ovens or any appliance that would generate a idect heat source.
- Halogen lighting equipment
- Candles; incense, outdoor gills, or any other type of open flame or open coildevice
- Explosives, fireworks, firearms, or ammunition

* This applies to all candles, including Shabbat and Hanukkah candles. Shatatband Hanukkah candles may be kindled only in officially designated areas. An incandescent eletric light should be utilized in student rooms for Shatatedias8ec sssl-ors. At \$\$

EMERGENCY EACUATION:

Housing Procedures for Evacuation in Case of a Fire

- Keep calm. Do not paic. Notify the Fire Department as soon as possible. Fire Department personnel will be on the scene of a fire within minutes of receiving an alarm.
- If your building is equipped with a fire alarm andthat alarm is sounded, you should evacuate the building in accordance with the procedures outlined in the Fire Safety Notice affixed to the back of the room/suite entry door. WHENA FIRE ALARM SOUNDS, ALWAYS EQUATE THE BUILDING.
- Because flame, heat, ad smoke rise, general

building (i.e., fire exits, stairways, alarm pull stations), as well ashe fire safety procedures for the building.

Residents should report any problems or inappropriate behavior observed to the Beren CampusSecurity Department, including damaged or tampered with fire alarms, removal of fire exits signs, missing fire extinguishers, and behavior that compromises the safety of the community.

List of the titles of each person or organization to which stu dents and employees should report that a fire occu rred.

At the onset of a fire, students and employees should immediately rept all fires to the New York City Fire Department by dialing 911 or activating the fire systems. The curity Department should be notified as well by calling 917326-4885.

Any plans for improvements in fire safety, should the University determine the at improvements are necessary Not at this time.

Each University campus will distribute its Annual Fire Safety Rport and AnnualSecurity Report to all current students and employees bOctober 1 of each year. The repostwill be posted on the University's website on the Security Department's page at <u>http://www.yu_.edu/safety-security/</u> and can be accessed by clicking on the Reports link A notice will be distributed to all students and employee briefly describing the reports.

Annual Report to the U.S. Department of Education

As required by federal law, the University reports annually to the Education Department the fire statistics listed herein for Beren oncampus student housing as well as fire statistics for on-campus student housing for its other campuses. The University reports these statistics through the Education Department's web-based data cdection system. Statistics for the University and other schools are available at the Office of Post Secand Education's web pageat http://ope.ed.gov/campussafety/#/.

Daily Fire Log

As required by federal law, each University ampus maintains an easily understood written Daily Fire Log. Themain office of the Beren Campus Serity Department, located at 50 East 34^h